

# Product Revision – MDA

---

Raytheon part number	16-02210-001 (L)
Telecore part number	2AA-00400-0022
Latest revision	2AA-00453-1903
Distribution	MDA WebFile_0022 Prd Rls_0022 Md Ctrl Doc_Sftwr 1903.zip

**Warning** – Both MDAs in a linked pair must have the same version installed in order to support all features properly.